

Windows Printer Settings for Zebra GX430t

×

Open Devices and Printers

Right click on the ZDesigner GX430t printer and click 'Printing Preferences'

On the 'Printing Preferences' menu, set the 'Size' to:

2.50 for Width

1.00 for Height

ZDesigner GX430t Printing Preferences

	barcooe ron				Comman	d Port	a.	
Custom Commands		Impo	Import/Export settings		lo	ols D.u	ls About	
opuoris	Advanced	Setup	Litne	ng	Stocks	Phn	ter Memory	
Settings	Georgenerer							
N	lo. Of Copies	(0					
Speed:		4. V		"/s				
Darkness:			15	~				
S	tocks:		User def	ined			\sim	
Paper For	mat	22-0		1.1.1				
() cm			portra	5e			
0	mm	1.	(THE)	Olands	cape			
0	inch	11	WRCE	rotati	e 180°			
Size —								
٧	Vidth:	2.50						
H	leight:	1.00						
Unprintab	le Area —							
L	eft:	0.00		Top:	0	0.00		
	light:	0.00		Bottom	6	0.00	- 1	
F		the second se						

Next click on the 'Advanced Setup' tab

Click the 'Calibrate' button in the bottom right to calibrate label size.

🖶 ZDesigr	ner GX430t P	rinting F	Prefer	ences				×			
Barcode Fonts				Command Fonts							
Custom C	ustom Commands Import/			Export settings Tool			ls	About			
Options	Advanced	Setup	Dit	nering	Sto	Stocks		ter Memory			
Use pri Operation	inter settings Mode ———										
0	Tear off				Applicator						
C	Rewind				◯ Stream						
C	O Peel Off				○ RFID						
0	Linerless Peel				O Cutter						
C	 Linerless Cut 				Group Quantity: 0						
C	Linerless Delay Cut				Advanced **						
	Mirror Image	B			iverse	•					
Media Typ	e										
0	Thermal Tra	ansfer		OT	hema	al Direc	t				
Tracking I	Mode										
0	◯ Continuous			O Mark Sensing							
	Web Sensir	ng									
Adjustmen	t	-									
T	op	0.0	0	inch							
Т	ear Off	0.0	0	inch							
	ent Position	0.0	0	inch							
** Only va	alid for use wit	th Labelin	ng Soft	tware							
	Applicator			Other			Calibrate				
	OK				A	pply		Help			

In the lower section of this window, under 'Adjustment' set 'Top' to .06 and click Apply.

ZDesigner GX430t Printing Preferences									
Barcode Font		Command Fonts							
Custom Commands	Custom Commands Import			Export settings Tools					
Options Advanced	Setup	Dith	ering	Stock	s	Prin	ter Memory		
Use printer settings Operation Mode							,		
Tear off			O A	pplicato	r				
○ Rewind	Rewind			◯ Stream					
O Peel Off	Peel Off			○ RFID					
O Linerless Pe	○ Linerless Peel			◯ Cutter					
C Linerless Cu	Linerless Cut			Group Quantity:					
⊖ Linerless De	 Linerless Delay Cut 			Advanced **					
Mirror Image	Mirror Image			lnverse					
Media Type									
Thermal Transition	nsfer		OT	hermal l	Direct				
Tracking Mode									
◯ Continuous	O Mark Sensing								
Web Sensir	ng								
Adjustment									
Тор	0.0	6	inch						
Tear Off	0.0	0	inch						
Left Position	0.0	•	inch						
Left Foation	0.0	•	inch						
** Only valid for use with Labeling Software									
Applica	Applicator			Other			brate		
ОК	ОК				ancel Apply				