

# Bearing Mount Analysis

CID: AICX2600131339




6.5 x 12.0

4/23/2018 2:11 PM

BEARING 1

Condition:R



Backing Ring: Fitted



BEARING 2

Condition:R




Backing Ring: Fitted



BEARING 1

Condition:R

Backing Ring: Fitted



BEARING 2

Condition:R

Backing Ring: Fitted

